



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

| | |
|------------------|-------------------------|
| Permit Number: | C0070016 |
| Inspection Type: | PARTIAL |
| Inspection Date: | Thursday, May 13, 2010 |
| Start Date/Time: | 5/13/2010 9:05:00 AM |
| End Date/Time: | 5/13/2010 10:10:00 AM |
| Last Inspection: | Tuesday, April 27, 2010 |

Representatives Present During the Inspection:

OGM Pete Hess Environmental Scientist III

Inspector: Pete Hess, Environmental Scientist III

Weather: Sunny, cold; up-Canyon winds.

InspectionID Report Number: 2353

Accepted by: jhelfric

5/17/2010

Permittee: **MOUNTAIN COAL CO**

Operator: **MOUNTAIN COAL CO**

Site: **GORDON CREEK 2, 7 & 8 MINES**

Address: **HC 35 BOX 380, HELPER UT 84526**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **RECLAIMED**

Current Acreages

| | |
|--------|------------------------|
| 179.27 | Total Permitted |
| 34.15 | Total Disturbed |
| 32.52 | Phase I |
| 32.52 | Phase II |
| 0.73 | Phase III |

Mineral Ownership

- ☒ Federal
☐ State
☐ County
☒ Fee
☐ Other

Types of Operations

- ☒ Underground
☐ Surface
☐ Loadout
☐ Processing
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The site remains stable and is unchanged since the April inspection.

The site received a skiff of snow during the previous over-night period.

Inspector's Signature:

Pete Hess

Date

Thursday, May 13, 2010

Pete Hess, Environmental Scientist III

Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | Evaluated | Not Applicable | Comment | Enforcement |
|--|-------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Change, Transfer, Renewal, Sale | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Signs and Markers | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Topsoil | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.a Hydrologic Balance: Diversions | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.b Hydrologic Balance: Sediment Ponds and Impoundments | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.c Hydrologic Balance: Other Sediment Control Measures | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.d Hydrologic Balance: Water Monitoring | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.e Hydrologic Balance: Effluent Limitations | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Explosives | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Disposal of Excess Spoil, Fills, Benches | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Coal Mine Waste, Refuse Piles, Impoundments | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Noncoal Waste | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. Protection of Fish, Wildlife and Related Environmental Issues | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Slides and Other Damage | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 11. Contemporaneous Reclamation | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Backfilling And Grading | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 13. Revegetation | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 14. Subsidence Control | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 15. Cessation of Operations | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16.a Roads: Construction, Maintenance, Surfacing | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16.b Roads: Drainage Controls | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 17. Other Transportation Facilities | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 18. Support Facilities, Utility Installations | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 19. AVS Check | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 20. Air Quality Permit | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 21. Bonding and Insurance | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 22. Other | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

2. Signs and Markers

The Permittee ID sign was in place at the termination of the County road.

4.a Hydrologic Balance: Diversions

All of the reclamation channels were stable. None of the channels contained flow.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The reclaimed sediment pond area is stable. New plant growth is occurring. Jacob's Pond was observed as dry, although the bottom was damp.

4.d Hydrologic Balance: Water Monitoring

There was no flow observed in Bryner Creek.

13. Revegetation

New sprouting is occurring about the site.